

\$ 1 % O

06

! (Sn)	" 99.5%	" 99.0%	99.8%
# (Fe)	\$ 0.005%	\$ 0.01%	%0.01%
& (Cu)	\$ 0.002%	\$ 0.01%	%0.01%
' (Zn)	\$ 0.005%	\$ 0.01%	%0.01%
((As)	\$ 0.0002%	\$ 0.005%	%0.005%
) (Sb)	\$ 0.010%	\$ 0.015%	%0.015%
* (Pb)	\$ 0.02%	\$ 0.04%	%0.04%
+ (Bi)	\$ 0.01%	\$ 0.01%	%0.01%